ISSUE FOR STATUS CHECKED BY. APPROVED BY DATE. DATE. 2014/09/29 K.Takeuchi Official doc. SA Approved CHECKED BY. Y.Morita PREPARED BY. DATE. 2014/09/30 2014/09/30 DATE. 2014/09/29 2014/09/22 T.Ikeuchi

TECHNICAL REPORT	DOC. No.	EWT14362	P. 1 / 1
ISSUE FOR Nabtesco Customer		REVISED	
SUBJECT A mixing of MOLYWHITE RE00 and VIGOGREASE RE0			

1. Outline

There are instructions and directions for use related to the mixing of MOLYWHITE RE00 and VIGOGREASE RE0.

2. Instructions and directions for use

Mixing of MOLYWHITE RE00 and VIGOGREASE RE0 generates no problems, but the following important rules should be observed:

Please do not mix VIGOGREASE RE0 with unused (or short running time) MOLYWHITE RE00. If you do, strong vibrations or noises will occur due to clumping togetherof additives between both greases.

100 hrs should be the minimum for MOLYWHITE RE00's running time. If the MOLYWHITE RE00's running time has already exceeded 100 hrs most likely this negative phenomenon will not occur.

If strong vibrations or noises occur, you can resolve them by doing pre-conditioning interim operations.

Concerning troubled gear boxes using a mixture of MOLYWHITE RE00 and VIGOGREASE RE0, we have already made sure that there are no problems with reliability as we have conducted endurance testing.

	This document contains proprietary information and shall not be reproduced or disclosed in whole or in part or used for any purpose, without the direct prior written consent of Nabtesco Corporation.		
FMT-G035B-1/2	Nabtesco	Precision Equipment Company Engineering / Development Department	